

• Publishing System: TPAS

• Access date: 1/16/01

• Document ECN's: Latest Available



Kit Instruction— KDACVNORNC





Please Read

About the Manual Identifying Information on the Cover

The front cover displays pertinent identifying information for this manual. Most important, are the published manual number (part number) /ECN (date code). Generally, when a replacement manual is furnished, it will have the same published manual number, but the latest available ECN. This provides the user with the latest information applicable to his machine. Similarly all documents comprising the manual will be the latest available as of the date the manual was printed, even though older ECN dates for those documents may be listed in the table of contents.

When communicating with the Milnor factory regarding this manual, please also provide the other identifying information shown on the cover, including the publishing system, access date, and whether the document ECN's are the latest available or exact.

References to Yellow Troubleshooting Pages

This manual may contain references to "yellow pages." Although the pages containing troubleshooting procedures are no longer printed on yellow paper, troubleshooting instructions, if any, will be contained in the easily located "Troubleshooting" chapter or section. See the table of contents.

Trademarks of Pellerin Milnor Corporation

The following, some of which may be used in this manual, are trademarks of Pellerin Milnor Corporation:

Ampsaver®	Dye-Extractor®	Gear Guardian®	Milnet®	Staph-Guard [®]
Autolint®	Dyextractor [®]	Hands-Off®	Milnor®	System 4 [®]
Auto-Purge [®]	E-P Express®	Hydro-Cushion [®]	Miltrac	System 7 [®]
Autovac	E-P OneTouch®	Mildata®	Miltron	Totaltrol [®]
$CBW^{\scriptscriptstyle{\circledR}}$	E-P Plus®			

Comments and Suggestions

Help us to improve this manual by sending your comments to:


Pellerin Milnor Corporation Attn: Technical Publications P. O. Box 400 Kenner, LA 70063-0400


Fax: (504) 469-1849

Add Normally Open Clutch Valve 64046E6N, 72058J2N/J5N



Pellerin Milnor Corporation P. O. Box 400, Kenner, LA 70063-0400





ADDING THE NORMALLY OPEN VALVE IN THE CLUTCH CIRCUIT

- 1. Mount the new normally open, pilot valve directly under the existing clutch valve using the hardware supplied in the kit.
- 2. Wire the new normally open valve in parallel with the coil of the existing clutch valve.

The new normally open valve should have a "T" fitting screwed into Port 1. The existing clutch valve will now be tubed from Port 1 to the "T" fitting. The outlet of the "T" will then lead to the quick relief valve which feeds the clutch.

Port 2 on the new normally open valve will be plugged with a metal pipe plug.


Port 3 of the new normally open valve will be vented to atmosphere.

If for any reason the existing clutch valve seat fails, the new normally open valve will allow air to pass through Port 1 to Port 3 and to atmosphere, thus not inflating the clutch.

If the exhaust port (Port 3) on the new normally open valve is passing air when the clutch is not inflated, you must replace or rebuild the normally closed clutch valve immediately. (This is the valve with the green coil.)

If you have any questions, please call MILNOR Technical Support at 504-467-9591, ext. 75.

Attachment



IMR 28.98