



INPUT				OUTPUT		
TERMINALS	CONNECT	VOLTS	HZ	TERMINALS	NO LOAD	FULL LOAD
H1-H4	H4&H2, H3&H1	110	50	X3-X1	17.4	15.9
H1-H4	H4&H2, H3&H1	120	60	X3-X2	18.0	16.0
H1-H4	H2 & H3	220	50	X3-X1	17.4	15.9
H1-H4	H2 & H3	240	60	X3-X2	18.0	16.0