

**7676 DRYER BASKET (HIGH VOLTAGE)
V1000 INVERTER**

CONSTANT	VALUE	CONSTANT	VALUE
A1-01	2 Note 2	E1-06	60
A1-02	0	E1-07	3
A1-03	Note 1	E1-08	24
B1-01	1	E1-09	1.5
B1-02	1	E1-10	12
B1-03	0	H1-01	40
C1-01	6	H1-02	41
C1-02	4	H2-01	E
C2-01	1.0	H3-04	-25
C6-01	1	H3-13	.5
C6-02	2	H3-03	215
E1-01	480	L1-01	0
E1-03	F	L2-01	2
E1-04	89 Note 3	L3-04	0
E1-05	480		

Note 1: 2220 is initialize - otherwise 0
 Note 2: Set to 0 after programming
 Note 3: Adjust for speed 100% is 29 RPM