

PELLERIN MILNOR CORPORATION

P. O. BOX 400, KENNER, LOUISIANA 70063-0400, USA (504) 467-9591

SERVICE BULLETIN - FACSIMILE

REPLY TO PARTS & SERVICE:504-469-9777E-MAIL:SERVICE@MILNOR.COMDATE:October 25, 2004MILNOR REF NO.:FAX NO.:TO:Salesmen & Service ManagersFROM:Russ PoyCOMPANY:MILNOR DealersRETURN TO:Diane Schnauder, Service Dept.

SUBJECT: Single Station Press Hydraulic System Field Assembly Procedures

IMPORTANT INFORMATION FOR SINGLE STATION PRESS INSTALLERS

The hydraulic system will be leak free if it is assembled properly. The instructions are contained in the technical manual. We have become aware that in the case where a mechanical contractor other than our Dealer technician performs the assembly, the technical manual is not available at the time of assembly. In many cases leaks occurred after the press was placed in service.

Therefore, we are now attaching the instruction sheet (included in this bulletin) to the hydraulic tank. Additionally, we are shipping open end attachments for torque wrenches. Please make sure all installers fully understand these instructions. Voiding warranty may result from improper assembly.

Best regards,

PELLERIN MILNOR CORPORATION

Russell H. Poy Vice-President Engineering

RHP/das Attachment: B2T2004036/2004436N