Published Manual Number/ECN: H000000019/2001344N

- Publishing System: TPAS
- Access date: 1/24/02
- Document ECN's: Exact

Kit Instruction— KTRCGAM001





Please Read

About the Manual Identifying Information on the Cover

The front cover displays pertinent identifying information for this manual. Most important, are the published manual number (part number) /ECN (date code). Generally, when a replacement manual is furnished, it will have the same published manual number, but the latest available ECN. This provides the user with the latest information applicable to his machine. Similarly all documents comprising the manual will be the latest available as of the date the manual was printed, even though older ECN dates for those documents may be listed in the table of contents.

When communicating with the Milnor factory regarding this manual, please also provide the other identifying information shown on the cover, including the publishing system, access date, and whether the document ECN's are the latest available or exact.

References to Yellow Troubleshooting Pages

This manual may contain references to "yellow pages." Although the pages containing troubleshooting procedures are no longer printed on yellow paper, troubleshooting instructions, if any, will be contained in the easily located "Troubleshooting" chapter or section. See the table of contents.

Trademarks of Pellerin Milnor Corporation

The following, some of which may be used in this manual, are trademarks of Pellerin Milnor Corporation:

Ampsaver®	Dye-Extractor [®]	Gear Guardian®	Milnet [®]	Staph-Guard [®]
Autolint [®]	Dyextractor®	Hands-Off [®]	Milnor [®]	System 4 [®]
Auto-Purge [®]	E-P Express [®]	Hydro-Cushion [®]	Miltrac	System 7 [®]
Autovac	E-P OneTouch [®]	Mildata [®]	Miltron	Totaltrol [®]
$\operatorname{CBW}^{\mathbb{R}}$	E-P Plus [®]			

Comments and Suggestions

Help us to improve this manual by sending your comments to:

Pellerin Milnor Corporation Attn: Technical Publications P. O. Box 400 Kenner, LA 70063-0400

Fax: (504) 469-1849

CGA Monitor Replacement for the 76032 CBW Miltron

Parts included with the kit:

1 - 97A029A	#29 Job drill
5 - 15P105	Panhead thread cuts
5 - 27B175I	Plastic spacers
1 - 08MN080T	CGA Monitor

This kit is used to replace the 'old' style CGA monitor with the 'new' style CGA Monitor for the Miltron used on the 76032 CBW. Prior to beginning the replacement, it is necessary to familiarize yourself with all safety precautions in the Continuous Batch Washer and Miltron manuals; **please observe all safety precautions**. It is also imperative that these instructions are read prior to beginning the retrofit. While working on the Miltron, tag and lockout the power.

The monitor is supplied with 2 (each) Four Pin Molex Plugs (1 male & 1 female). Your Miltron may have a matching plug but DO NOT connect to it until you verify that it has 3 wires and those wires supply the following:

- Machine Ground
- 120 VAC (high)
- Neutral

These must match up with and connect to:

- Machine ground = green on monitor
- 120 VAC (high) = black on monitor
- Neutral = white on monitor

Connect the long gray cable with the "D" plug, to the video card. The connections are now complete. If the plugs do not match, do away with the plugs and connect directly.

If you should have any questions, please call Milnor Technical Support at (504) 467-9591 extension 276.

SWS08/22/01