

Published Manual Number/ECN: H00000037/2000104N


- Publishing System: TPAS
- Access date: 1/16/01
- Document ECN's: Exact



# Kit Instruction—

## KHKMSCB001

## KHSMSCB001



# Please Read

## About the Manual Identifying Information on the Cover

The front cover displays pertinent identifying information for this manual. Most important, are the published manual number (part number) /ECN (date code). Generally, when a replacement manual is furnished, it will have the same published manual number, but the latest available ECN. This provides the user with the latest information applicable to his machine. Similarly all documents comprising the manual will be the latest available as of the date the manual was printed, **even though older ECN dates for those documents may be listed in the table of contents.**

When communicating with the Milnor factory regarding this manual, please also provide the other identifying information shown on the cover, including the publishing system, access date, and whether the document ECN's are the latest available or exact.

## References to Yellow Troubleshooting Pages

This manual may contain references to "yellow pages." Although the pages containing troubleshooting procedures are no longer printed on yellow paper, troubleshooting instructions, if any, will be contained in the easily located "Troubleshooting" chapter or section. See the table of contents.

## Trademarks of Pellerin Milnor Corporation

The following, some of which may be used in this manual, are trademarks of Pellerin Milnor Corporation:

Ampsaver <sup>®</sup>	Dye-Extractor <sup>®</sup>	Gear Guardian <sup>®</sup>	Milnet <sup>®</sup>	Staph-Guard <sup>®</sup>
Autolint <sup>®</sup>	Dyextractor <sup>®</sup>	Hands-Off <sup>®</sup>	Milnor <sup>®</sup>	System 4 <sup>®</sup>
Auto-Purge <sup>®</sup>	E-P Express <sup>®</sup>	Hydro-Cushion <sup>®</sup>	Miltrac	System 7 <sup>®</sup>
Autovac	E-P OneTouch <sup>®</sup>	Mildata <sup>®</sup>	Miltron	Totaltrol <sup>®</sup>
CBW <sup>®</sup>	E-P Plus <sup>®</sup>			

## Comments and Suggestions

Help us to improve this manual by sending your comments to:

Pellerin Milnor Corporation  
Attn: Technical Publications  
P. O. Box 400  
Kenner, LA 70063-0400

Fax: (504) 469-1849

MSSM0515AE/93511

December 15, 1993

INSTRUCTION

SUBJECT: KHSMSCB001/KHKMSCB001 -  
REPLACEMENT SOAP CHUTE FOR S & K MODEL MACHINES

Enclosed is a new soap chute with splash deflector attached. It is designed to prevent water splash during draining on the early model S or K machines.

Listed on the enclosed P-ticket are those machines received by you. Please see that the old soap chute is replaced with this new design on the machines listed.

Upon return of the original soap chute, credit will be issued in full. Please reference the P-ticket number or attach the enclosed return tag with the original soap chute.

NOTE: WHEN INSTALLING THE SOAP CHUTES, DO NOT USE AIR OPERATED TOOLS.

Thank you.

PELLERIN MILNOR CORPORATION

LJT/das