


Published Manual Number/ECN: H25 0002A/2001046N

- Publishing System: TPAS
- Access date: 1/26/01
- Document ECN's: Latest Available







Please Read

About the Manual Identifying Information on the Cover

The front cover displays pertinent identifying information for this manual. Most important, are the published manual number (part number) /ECN (date code). Generally, when a replacement manual is furnished, it will have the same published manual number, but the latest available ECN. This provides the user with the latest information applicable to his machine. Similarly all documents comprising the manual will be the latest available as of the date the manual was printed, even though older ECN dates for those documents may be listed in the table of contents.

When communicating with the Milnor factory regarding this manual, please also provide the other identifying information shown on the cover, including the publishing system, access date, and whether the document ECN's are the latest available or exact.

References to Yellow Troubleshooting Pages

This manual may contain references to "yellow pages." Although the pages containing troubleshooting procedures are no longer printed on yellow paper, troubleshooting instructions, if any, will be contained in the easily located "Troubleshooting" chapter or section. See the table of contents.

Trademarks of Pellerin Milnor Corporation

The following, some of which may be used in this manual, are trademarks of Pellerin Milnor Corporation:

Ampsaver®	Dye-Extractor®	Gear Guardian®	$Milnet^{^{\circledR}}$	Staph-Guard®
Autolint®	Dyextractor [®]	Hands-Off®	$Milnor^{^{\circledR}}$	System 4 [®]
Auto-Purge [®]	E-P Express [®]	Hydro-Cushion [®]	Miltrac	System 7 [®]
Autovac	E-P OneTouch®	Mildata [®]	Miltron	Totaltrol [®]
$\operatorname{CBW}^{\scriptscriptstyle{\circledR}}$	E-P Plus®			

Comments and Suggestions

Help us to improve this manual by sending your comments to:

Pellerin Milnor Corporation Attn: Technical Publications P. O. Box 400 Kenner, LA 70063-0400

Fax: (504) 469-1849

52038 DOOR GASKET CONVERSION INSTRUCTIONS

APPLICABILITY: 52038WEU machine door gaskets

SCOPE: Instructions for converting old to new door gaskets

Because of the unavailability of door gasket, 03 25085, it will be necessary to custom modify the gasket we do have available, 03 25085A, to fit your machine. This is accomplished by removing a section (as much as necessary for proper fit) of the new gasket and bonding the two ends back together with the adhesive provided.